Philips Firmware Upgrade Information

Upgrade for types:	DVDRW824K/00	→ Drive type number on label.
Upgrade for string:	DVDR824P	→ Drive name as seen in Windows ™
From firmware:	P1.x	
To new firmware:	P1.5	
Date:	5 August 2005	

Table of contents:

1. Version History 2
2. Important Warning: 2

Philips does not and can not warrant the performance of/the results you may obtain using this software. At no time, Philips can held liable for any damages including (but not limited to) lost profits or consequentional damages or for any claim by any other party.

(c) 2005 N.V. Philips Consumer Electronics

1. Version History

First version is P1.0

Form firmware P1.0 to P1.2 (P1.1 does not exist)

- Improved writing quality on some DVD+R media.

Changes from firmware P1.2 to P1.3

- Improved recognition of copied DVD discs.
- Corrected write speed shown in CDSpeed.
- Improved reading of table of contents on DVD-R and DVD-RW.
- InCD can now format new DVD+RW discs.
- Improved writing quality on some DVD+R and DVD+RW media.

Changes from firmware P1.3 to P1.4

- Released 8 November 2004.
- Playing of recorded DVD+R Double Layer discs is added

Changes from firmware P1.4 to P1.5

- Released 5 August 2005.
- Improved writing quality on unknown DVD+R and DVD+RW media by using an improved algorithm.

2. Important Warning:

This upgrade is only valid if you are using a P1.x firmware.

When you have a DVDR824P drive with firmware P2.x, you can not use this upgrade.
Choose the DVDRW824K/20 model to find your latest upgrade.

When you have a DVDR824DP drive with firmware P3.x, you can not use this upgrade.
Choose the DVDRW824K/40 model to find your latest upgrade.

For more info, see the included document:
Upgrading Troubleshooting and Frequenly Asked Questions.pdf

(c) 2005 N.V. Philips Consumer Electronics