Philips Consumer Electronics

Philips Firmware Upgrade Information

Upgrade for type:	DVDRW208K/00	→ Drive type number on label.
Upgrade for string:	DVDRW1208	→ Drive name as seen in Windows ™
From firmware:	1.xx	
To new firmware:	1.92	
Date:	2nd February 2005	

Table of contents:

1. Version History 2



Warning:
Please close all running software application and eject any discs from the drive you want to upgrade.
Philips does not and can not warrant the performance of/the results you may obtain using this software.
At no time, Philips can held liable for any damages including (but not limited to) lost profits or consequentional damages or for any claim by any other party.
Do not try to upgrade other then foreseen drives.

v08

(c) 2005 N.V. Philips Consumer Electronics

1. Version History

Changes from firmware 1.37 to 1.41

- Fixed a possible format problem on CD-RW.

Changes from firmware 1.41 to 1.75

- Improved writing quality on 32x CD-R discs from Ricoh.
- Improved writing quality on CD-RW discs from Acer.
- Improved writing quality on DVD+RW discs from CMC and Ritek.

Changes from firmware 1.75 to 1.90

- Reads also multi-session DVD+R discs.
- Improved writing quality on 4x DVD+RW discs from Mitsubishi (MCC) and Ricoh.

Changes from firmware 1.90 to 1.92

- Improved writing quality on DVD+RW discs.

(c) 2005 N.V. Philips Consumer Electronics
www.philips.com/support