Philips Firmware Upgrade Information

Upgrade for type:	ED16DVDRK/00 ED16DVDRK/05 (UK)	→ Drive type number on label.
Upgrade for string:	ED16DVDR	→ Drive name as seen in Windows ™
From firmware:	B5Sx	
To new firmware:	B5S7	
Date:	19 Oct 2005	

Version History

Changes from firmware B5S2 to B5S3

- Improved writing quality on DVD+R 8x with adip code "Philips 081"
- Improved writing quality on DVD+R 2,4x with adip code "MCC001"
- Improved playability of some audio CDs.

Changes from firmware B5S3 to B5S6

- Released 15 December 2004.
- Improved writing quality on DVD+R 8x with adip code "TDK002"
- Improved playability of some audio CDs.

Changes from firmware B5S6 to B5S7

- Released 19 October 2005.
- Improved stability of the drive.
- Improved digital audio extraction from some discs.
- Improved recognition of low quality discs.
- Improved writing quality on several DVD+R, DVD+R Double layer and DVD+RW



Philips does not and can not warrant the performance of/the results you may obtain using this software. At no time, Philips can held liable for any damages including (but not limited to) lost profits or consequentional damages or for any claim by any other party.

v10

(c) 2005 N.V. Philips Consumer Electronics